Poles Changed out by
(Chugach) Pioneer

2001 / 2002
Dec JAN

F-22-10
F3-19-12
F6-185
F2-13
F2-31
F2-27
F2-11-20
F2-34
F2-23
F2-22
F2-21
F2-16
F1-38
F1-6
F1-5
F3-2
F3-1
ARES
F2-22-45
F3-3
F4-7
F3-83
F2-53
F2-52
F3-56-10
F3-56-18
F3-56-4
F3-56-6

Poles Changed out

Pole #		
F2 P1	Changed Oct 96	
F2 P36	"	
F2 P37	"	
F2 P14D	"	
F3 P5	"	
GF2 P2	"	
GF2 P3	"	
GF2 P4	"	
GF2 P27	"	
GF2 P33	"	
GF2 P9	APR 96	
GF2 P10	"	
GF2 P57	"	
F2 P13D	July 97	
F2 P252	"	
F3 P352	"	
F3 P353	"	
F3 P354	"	
F3 P355	"	
F2 P29	"	
F2 P33	"	
F3 P295	"	
F3 P327	"	
FG P1	Aug 97	
F2 P40	"	Hit by Lightning
GF P49	"	
GF P52	"	
GF P55	"	
F2 P119	"	
	"	

Poles Changed out

Changed Aug 97

Pole #	
GP1	↓
F3P75	"
F3P88	"
F3P97	"
F3P209	"
F2P95	"
	Sep 97

Poles Changed out by SNL 1999

F3373	"
F3384	"
F3397	"
F3400	"
F3426	"
F3431	"

List given to COE for contractor bid 7-30-99

Manzano Area Pole Replacements				
Pole Number		Condition		Location
	Changed			
F2179	✓	3		SW of 30117
F2193	✓	3		E. of 30136
F2194	✓	3		NE of 30136
F2201	✓	3		4th pole W. of SW 746
F2214	✓	3		CTA Driving Area
F2216	✓	3		E of 30109
F2245	✓	5		Between Stables and Glf Crse
F2258A	✓	5		H-fix at glf crse
F2261	✓	3		Between glf crse and pump sta. by road
F2281	✓	4		glf crse maint. Bldg. Xfmr pole
F220	✓	4		SW of 37055 inside WSA
GF258		3		Middle of Saddle (difficult)
F3356	✓	3		Coyote Canyon
F3364	✓	3		Coyote Canyon
F3366	✓	3		Coyote Canyon
F3368	✓	3		Coyote Canyon
F3375	✓	3		Coyote Canyon
F3379	✓	3		Coyote Canyon
F3399		3		Coyote Canyon
F3401	✓	3		Coyote Canyon
F3405		3		Coyote Canyon
F3415	✓	3		Coyote Canyon
F3427	✓	3		Coyote Canyon
F3428	✓	3		Coyote Canyon
F3432	✓	3		Coyote Canyon
F3435	✓	3		Coyote Canyon
F3437	✓	3		Coyote Canyon
F3439	✓	3		Coyote Canyon
F3446	✓	3		Coyote Canyon
F3452	✓	3		Coyote Canyon
F3454	✓	3		Coyote Canyon
F3456	✓	5		Coyote Canyon
F3459	✓	3		Coyote Canyon
F3465	✓	3		Coyote Canyon
F3469	✓	3		Coyote Canyon
F3479	✓	3		Coyote Canyon
3-89-325	✓	5		4104 Mercury Dr
3-12-34-1	✓	5		15th and D
3-89-333	✓	5		4110 Mercury
3-89-483	✓	5		4001 Greenhouse
3-55-32	✓	5		7501 Bradshaw
3-12-24-3		5		W of Sub 3 46kV guy pole
3-23-865		5		?
6-255	✓	5		?
3-84-333		5		?

Condo Fee Pole Replacements

Pole Number	Condition
F2179	3
F2193	3
F2194	3
F2201	3
F2214	3
F2216	3
F2245	5
F2258A	5
F2261	3
F2281	4
F220	4
GF258	3
F3356	3
F3364	3
F3366	3
F3368	3
F3373	3
F3375	3
F3379	3
F3384	3
F3397	5
F3399	3
F3400	3
F3401	3
F3405	3
F3415	3
F3426	3
F3427	3
F3428	3
F3431	3
F3432	3
F3435	3
F3437	3
F3439	3
F3446	3
F3452	3
F3454	3
F3456	5
F3459	3
F3465	3
F3469	3
F3479	3
F1300	3

6-14-99

143

Poles Identified to be changed but on dead feeder #1
No need to change at this time

F17	3
F120	3
F129	3
F146	3
F198	3
F1104	3
F1142	3
F1166	3
F1268	3
F1273	3
F1299	3
F1305	3
F1307	3