

QUESTIONS FOR ELMENDORF/KULIS #5

33 J-46-30 Points of Demarcation:

Phoenix: There appears to be a typographical error. Please clarify whether ownership does or does not include the fused cutout.

Ownership does not include the fused cutout. The POD is on the line side of the fused cutout.

Seattle: It appears that the point of demarcation is on the load side of the fused cutout switch, yet the utility does not own the fused cutout switch. Please indicate whether this is an error. If it is not an error, how can the utility be held responsible for operation of a component which it does not own, or operate?

Ownership does not include the fused cutout. The POD is on the line side of the fused cutout.

Douglas: It appears that the utility will own a fused cutout, a transformer, and some secondary conductors to a facility which are on the Government side of the POD. This calls into question the meaning of the term "Point of Demarcation" Please clarify whether this is an error, and if not, what is the meaning of the utility owning facilities on the Government side of a point of demarcation.

Ownership does not include the fused cutout. The POD is on the line side of the fused cutout.

Facilities 3062, 3064, 3068, and 3040: It appears that the POD is on the load side of the line fuse serving transformer 201, but the utility does not own the line fuse. Please explain how the utility can be responsible for the operation of a fuse which it does not own.

The point of demarcation is the line side of the line fuse serving transformer 201, and the line side of the fused cutout for transformer 1550 for housing along Arctic Warrior Drive. Ownership does not include the line fuse or the fused cutout.